DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: xx.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-019930 Address: 333 Burma Road **Date Inspected:** 27-Sep-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

CWI Name: CWI Present: Yes Mr. Wang Jie. No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Orthotropic Box Girder (OBG) Bay 14~16

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Raghavendra Reddy was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

This QA Inspector observed the following work in progress:

BAY # 14:

Flux Cored Arc Welding (FCAW) welding of welds joint AP3020-001-014,015, and Welder is identified as 201215,202122. ABF Quality Control (QC) is identified as Mr. Shao Jian Yuan. The welding variables appeared to comply with the Applicable WPS-B-T-2132.

FCAW welding of Base metal Buildup for Miss cutting area(Plate BP3070A 13CW), And Critical Welding Repair Report(CWR) B-CWR1911, Welder is identified as 066746. ZPMC Quality Control (QC) is identified as Mr. Wang Jie. The welding variables appeared to comply with the Applicable WPS-345-FCAW-1G(1F)-FCM-Repair.

FCAW welding of welds joint VP3016-001-013, And Welder is identified as 066763, ZPMC Quality Control (QC) is identified as Lv Li Qing. The welding variables appeared to comply with the Applicable WPS-B-T-2232-TC-U4b-F.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Submerged Arc Welding (SAW) welding of welds joint SEG3014-004, and Welder is identified as 045270. ABF Quality Control (QC) is identified as Mr. Lv Yun. The welding variables appeared to comply with the Applicable WPS-B-T-2221-B-L2C-S-2.

BAY#16


F.

FCAW welding of welds joint LD3035-001-023(13BW), Welder is identified as 045143. ABF Quality Control (QC) is identified as Mr. LLi Shi You. The welding variables appeared to comply with the Applicable WPS-B-T-2233-TC-U5-

FCAW welding of welds joint LD3033-001-037(13CW), Welder is identified as 045280. ABF Quality Control (QC) is identified as Mr. LLi Shi You. The welding variables appeared to comply with the Applicable WPS-B-T-2233-TC-U5-F.

FCAW welding of welds joint LD3032-001-032(13BW), Welder is identified as 040344. ABF Quality Control (QC) is identified as Mr. LLi Shi You. The welding variables appeared to comply with the Applicable WPS-B-T-2233-TC-U5-F.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.





Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng (15921845703), who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Tharikoppada, Reddy Quality Assurance Inspector **Reviewed By:** Miller,Mark QA Reviewer